












MOTOR CONNECTOR	
1	Phase "U"
2	Phase "V"
3	Phase "W"
4	Earth



SPINDLE CONNECTIONS	
1	1/4" Gas. INLET-OUTLET MOTOR COOLANT (Water cooler)
2	1/4" Gas. INLET-OUTLET MOTOR COOLANT (Water cooler)
3	1/4" Gas. OIL INLET PISTON (40 bar max) / Hydraulic in
4	1/8" Gas. AIR INLET FRONT PURGE see scheme (Air Cutter)
5	1/4" Gas. OIL INLET FOR PISTON BACK (40 bar max) / Hydraulic out
THIS PRESSURE HAVE TO BE PRESENT TO ENSURE THE POSITION DURING CUTTING WORKS !	



ROTATING UNION CONNECTIONS:	
F	Inlet tool cooling 1/4" Gas
H	Air inlet for cleaning taper 1/4" Gas
H	Drainage 1/8" Gas

POWER LOSS 1330 Watt 1144 Kcal/hr